










SAFEWAY

Yes vise




夾持範圍示意表 Opening Capacity






L	300			400			500			600			700		
K	60	72	100	60	72	100	60	72	100	60	72	100	60	72	100
C	4	3	2	5	4	3	6	6	4	7	7	5	8	8	6
P		3	2		4	3		5	3~4		6	4		6~7	5
W×J	60×25	72×25	100×50	60×25	72×25	100×50	60×25	72×25	100×50	60×25	72×25	100×50	60×25	72×25	100×50
W×J1	60×50	72×50	100×75	60×50	72×50	100×75	60×50	72×50	100×75	60×50	72×50	100×75	60×50	72×50	100×75



L	300			400			500			600			700		
K	60	72	100	60	72	100	60	72	100	60	72	100	60	72	100
C							6	6		6	6		6	6	
W×J							145×25	155×25		165×25	175×25		150×25	160×25	
W×J1							145×50	155×50		165×50	175×50		150×50	160×50	



L	300			400			500			600			700		
K	60	72	100	60	72	100	60	72	100	60	72	100	60	72	100
C	4	2		4	4		4	4	4	4	4	4	4	4	4
W×J	140×25	300×25		170×25	180×25		235×25	240×25	230×50	275×25	280×25	280×50	330×25	340×25	330×50
W×J1	140×50	300×50		170×50	180×75		235×50	240×50	230×75	275×50	280×50	280×75	330×50	340×50	330×75



L	300			400			500			600			700		
K	60	72	100	60	72	100	60	72	100	60	72	100	60	72	100
C	2	2	2	2~3	2~3	2~3	2~3	2~3	2~3	2~4	2~4	2~4	2~4	2~4	2~4
W×J	300×25	300×25	300×50	400×25	400×25	400×50	500×25	500×25	500×50	600×25	600×25	600×50	700×25	700×25	700×50
W×J1	300×50	300×50	300×75	400×50	400×50	400×75	500×50	500×50	500×75	600×50	600×50	600×75	700×50	700×50	700×75



SAFEWAY

Yes vise

使用範例 (立式加工機) Example (For Vertical Machine)





SAFEWAY

Yes vise

使用範例 (臥式加工機) Example (For Horizontal Machine)

